



**Case Study Category:** MPWW

**Case Study Title:** Evaluation and Scoring of Sewer Segment at City of Phoenix Water Services Department (CPWSD)

**Utility Name:** City of Phoenix Water Services Department

**Case Study Abstract:** This case study introduces the evaluation and scoring methods used for sanitary sewer segments at City of Phoenix Water Service Department. This case study covers the scoring standards and impact factors that are based on the experience of United Research Services (URS) and City of Phoenix in evaluating the sanitary sewer segments. Based on these standards and scoring methods, a list of segments was selected for rehabilitation or repair. This case study also introduced the differences of scoring method between the URS and the National Association of Sanitary Sewer Companies.

**Case Study Link:** <http://waterid.org/content/evaluation-and-scoring-sewer-segment-city-phoenix-water-services-department-cpwsd>