



Case Study Category: CADW

Case Study Title: Fulton Pump Main Condition Assessment in the Portland Water Bureau

Utility Name: Portland Water Bureau

Case Study Abstract: This case study is based on the utilization of acoustic technologies for condition assessment in the Fulton pump main at Portland Water Bureau. According to obtained results, this main has a higher-than expected operating safety factor.

Case Study Link: <http://waterid.org/content/fulton-pump-main-condition-assessment-portland-water-bureau>