



Case Study Category: REDW

Case Study Title: Basis of Design Report for Portland Heights Pump Main

Utility Name: Portland Water Bureau

Case Study Abstract: This case study summarizes the basis of design report of a pump main in Portland, OR. The report details key considerations and the analysis of alternatives for the rehabilitation or replacement of the pump main.

Case Study Link: <http://waterid.org/content/basis-design-report-portland-heights-pump-main>