



Case Study Category: REWW

Case Study Title: Baltimore County Sliplining Project

Utility Name: Baltimore County Department of Public Works

Case Study Abstract: This case study is about a small sliplining project in Baltimore County. The Host pipe was 54" and the carrier was 50". The project ran into some unforeseen challenges that were afterwards successfully overcome.

Case Study Link: <http://waterid.org/content/baltimore-county-sliplining-project>