



Case Study Category: CADW

Case Study Title: Steel pipe inspection for Condition Assessment in Seattle Water Department

Utility Name: Seattle Public Utilities

Case Study Abstract: This case study summarizes some prioritization techniques utilized in Seattle Public Utilities (SPU) circa 1980. It is interesting to explore some of the techniques utilized and compare them with the actual approach to condition assessment and pipe asset prioritization.

Case Study Link: <http://www.waterid.org/content/steel-pipe-inspection-condition-assessment-seattle-water-department>