



Case Study Category: COSTDW

Case Study Title: Cost Case Study (Aurora, CO; Dig and Replace; C900 PVC): 2010 Annual Waterline Replacement

Utility Name: Aurora, CO

Case Study Abstract: This project covers replacing approximately 31,400 linear feet of existing water mains, including valves, fittings, and fire hydrants at various locations along residential streets in the City.

Case Study Link: <http://waterid.org/content/cost-case-study-aurora-co-dig-and-replace-c900-pvc-2010-annual-waterline-replacement>