



Case Study Category: CostWW

Case Study Title: Cost Case Study (Idaho Falls, ID; Excavation): 2012 Water Line Replacements (1st and Boulevard)

Utility Name: Idaho Falls, ID

Case Study Abstract: Replacement of water/sewer piping and appurtenances at 1st and Boulevard in the City of Idaho Falls, ID. The project also included street, sidewalk, curb and gutter, and incidental repairs e.g. landscaping

Case Study Link: <http://waterid.org/content/cost-case-study-idaho-falls-id-excavation-2012-water-line-replacements-1st-and-boulevard>