



Case Study Category: CostWW

Case Study Title: Cost Case Study (Fort Morgan, CO; Manhole Grout, Cementitious Reconstruction, Liners) 2011 Sanitary Sewer Manhole Rehabilitation Services

Utility Name: Fort Morgan, CO

Case Study Abstract: In general, the work will primarily consist of rehabilitation of sanitary sewer manholes. All interior surfaces (including benches) of new sanitary sewer mains and isolated service taps manholes shall be given an interior protective coating. Surface preparation and protective coating shall be in accordance with Standard Specifications Sewer Manhole Rehabilitation. These manholes are located within easements, in lanes, vegetated areas, landscaped yards, and throughout the City.

Case Study Link: <http://waterid.org/content/cost-case-study-fort-morgan-co-manhole-grout-cementitious-reconstruction-liners-2011-sanitar>