

Case Study Category: CostWW

Case Study Title: Cost Case Study (Delaware, OH; Joint and Lateral Connection

Grouting, CIPP): 2011 Sanitary Sewer Improvements Grouting Lining Project

Utility Name: Delaware, OH

Case Study Abstract: 2442 lf of 8" CIPP, reinstatement and grouting of 49 lateral connections, 12 manhole chimney seals, and testing and grouting of 230 joints in 10", 8", and 6" pipes.

Case Study Link: http://waterid.org/content/cost-case-study-delaware-oh-joint-and-lateral-connection-grouting-cipp-2011-sanitary-sewer-i