



Case Study Category: CostWW

Case Study Title: Cost Case Study (Cuyahoga County, OH; Pipe Bursting, Replacement)
Fernhill Sanitary Sewer Improvement 54-A

Utility Name: Cuyahoga County, OH

Case Study Abstract: This project replace an existing 1920's sanitary sewer that has failed due to age. The sanitary sewer is part of an over/under system and leakage from the failed storm sewer above is leaking into the failed sanitary pipe, resulting in backups and overflows. The configuration of the sewers will require replacement of the storm as well as the sanitary.

Case Study Link: <http://waterid.org/content/cost-case-study-cuyahoga-county-oh-pipe-bursting-replacement-fernhill-sanitary-sewer-improve>