



Case Study Category: CAWW

Case Study Title: Use of Closed Circuit Television Inspection of the Sanitary Sewer System by the County of Los Angeles Department of Public Works in Malibu, California

Utility Name: County of Los Angeles Department of Public Works

Case Study Abstract: This case study covers part of the work done for the County of Los Angeles Department of Public Works Consolidated Sewer Maintenance District Condition Assessment Program. This program involves inspection of the sanitary sewer system with closed-circuit television inspection. The project overview of the Malibu district is included, as are the quick maintenance and quick structural rating report priority lists.

Case Study Link: <http://waterid.org/content/use-closed-circuit-television-inspection-sanitary-sewer-system-county-los-angeles-department>