



Case Study Category: CAWW

Case Study Title: Condition Assessment of Large Diameter Lined concrete sewers in Phoenix, AZ

Utility Name: City of Phoenix Water Services Department

Case Study Abstract: This case study describes the use of visual technologies (CCTV) for condition assessment of 30-inch or larger diameter sewers in the city of Phoenix, AZ. Diverse technologies were considered for this project, but CCTV was chosen due to cost considerations.

Case Study Link: <http://www.waterid.org/content/condition-assessment-large-diameter-lined-concrete-sewers-phoenix-az>