



**Case Study Category:** CAWW

**Case Study Title:** Condition Assessment Report of PVC-Lined concrete sanitary sewers using CCTV in Phoenix, AZ

**Utility Name:** City of Phoenix Water Services Department

**Case Study Abstract:** This case study describes the use of closed-circuit cameras for inspection and condition assessment of PVC-lined sewers in the City of Phoenix, Arizona.

**Case Study Link:** <http://www.waterid.org/content/condition-assessment-report-pvc-lined-concrete-sanitary-sewers-using-cctv-phoenix-az>