



**Case Study Category:** CAWW

**Case Study Title:** Sewer Inspection using Smoke Testing in San Antonio, TX

**Utility Name:** San Antonio Water System

**Case Study Abstract:** This case study describes the use of smoke testing for leak detection in sewers at San Antonio, Texas. Smoke testing is a basic technique, which can be very cost efficient in specific cases.

**Case Study Link:** <http://www.waterid.org/content/sewer-inspection-using-smoke-testing-san-antonio-tx>