



Case Study Category: CADW

Case Study Title: Inspection and Condition Assessment of the 54-inch Northwest Water Transmission Main in Baltimore City

Utility Name: Baltimore City Department of Public Works

Case Study Abstract: This case study shows the utilization of three types of condition assessment technologies (Visual, Sounding, and Electromagnetic) in a drinking water transmission main in Baltimore City, MD.

Case Study Link: <http://www.waterid.org/content/inspection-and-condition-assessment-54-inch-northwest-water-transmission-main-baltimore-city>