



**Case Study Category:** CADW

**Case Study Title:** Use of Noise Correlators for Condition Assessment of Water Mains in Billings, MT

**Utility Name:** Department of Public works, Billings

**Case Study Abstract:** The use of noise correlators for condition assessment of water pipes is described for a project in Billings

**Case Study Link:** <http://www.waterid.org/content/use-noise-correlators-condition-assessment-water-mains-billings-mt>